Sustainable Test, Control and Measurement Systems

Reimar Spohr

[PhysicsConsult](#)

[Certified LabVIEW Associate Developer](#) (2012-2014)

1. Discussion phase

   - Discuss required properties and methods
   - Discuss tentative user interface and flow diagram
   - Discuss boundary conditions and required hardware

2. Development phase

   - Develop operative user interface
   - Develop system specification sheet
   - Develop software

3. Commissioning phase

   - Test system in working environment
   - Modify to meet specifications
   - Establish system documentation